

REPLACEMENT FOR

**BUICK CENTURY '99  
CHINA TYPE**

**132-1101-LD**

HEAD LAMP  
R 92682  
L 92683  
PCS CFT



H1/H1/P21W/P21W/W5W

TBA

REPLACEMENT FOR

**BUICK CENTURY '03  
CHINA TYPE**

**132-1104-LD**

HEAD LAMP  
R  
L  
PCS CFT



H1/H7/W5W

TBA

REPLACEMENT FOR

**BUICK GL8 '94  
CHINA TYPE**

**132-1103-LD**

HEAD LAMP  
R  
L 16530511  
PCS CFT



H4/W5W

TBA

**132-2001**

FOR LAMP  
R 10292680  
L 10292681  
PCS CFT



H3

TBA

'97

**132-2002**

FOR LAMP  
R  
L  
PCS CFT



H3

TBA

**132-1103-LDH**

HEAD LAMP  
R  
L  
PCS CFT



H4/W5W

TBA

**132-1901**

TAIL LAMP  
R  
L  
PCS CFT



TBA

'2000

**442-1402N-C**

SIDE LAMP  
100PCS 0.90CFT



WY5W

**132-1501-U**

CORNER LAMP  
R  
L 16530275  
10PCS 4.64CFT



PY21W

**132-1903**

TAIL LAMP  
R  
L  
PCS CFT



P21W/P21/5W/W5W

TBA

**132-1902**

TAIL LAMP  
R  
L  
10PCS CFT



TBA



REPLACEMENT FOR

**BUICK GL8 '99  
CHINA TYPE**



REPLACEMENT FOR

**CAPERICE '00**

REPLACEMENT FOR

**LOVA '06**

**132-1102-LD**  
HEAD LAMP  
R  
L  
PCS CFT



H4/PY21W/W5W **TBA**

**332-11A3-U**  
HEAD LAMP  
R 92048542  
L 92055107  
4PCS 4.98CFT



H4/H1/PY21W/W5W

**235-1104-LD** SA-TYPE  
HEAD LAMP  
R  
L  
PCS CFT



H4/PY21W/W5W **TBA**

**132-1902**  
TAIL LAMP  
R  
L  
10PCS CFT



**TBA**

**132-1904**  
TAIL LAMP  
R  
L  
PCS CFT



P21W/PY21W/W16W/P21/5W **TBA**







REPLACEMENT FOR

## OPTRA '04

GM

<p><b>222-1114-LD-EM</b> NUBIRA 1600 CC 1800 CC HEAD LAMP R 96458810 L 96458809 6PCS 6.73CFT</p>  <p>H1/H7/PY21W/W5W</p>		
<p><b>222-1114-LD-E</b> NUBIRA HEAD LAMP R 96458814 R 96425288 L 96458813 L 96425287 6PCS 6.73CFT</p>  <p>H1/H7/PY21W/W5W</p>		
<p><b>235-1402N-AE</b> SIDE LAMP M1A032D1 96337460 PCS CFT</p>  <p>WY5W TBA</p>		
<p><b>222-1914-UE</b> NUBIRA 1600 CC TAIL LAMP R 96551226 L 96551225 6PCS 4.69CFT</p>  <p>12V27/8W/12V27/8W/12V27W/12V27W</p>		
<p><b>222-1915-UE</b> NUBIRA 1800 CC TAIL LAMP R 96551224 L 96551223 6PCS 5.16CFT</p>  <p>P21/5W/P21/5W/P21W/P21W/PY21W</p>		