

LANOS II

REPLACEMENT FOR

222-1404P-AE-C
SIDE LAMP
50PRS 0.90CFT

OEM PARTS
222-1404N-UE



TUNING PARTS
222-1404P-AE-C



CLEAR W5W

DAEWOO

MATIZ II '01

REPLACEMENT FOR

222-1412P-B-VC
SIDE LAMP
50PRS 0.90CFT

OEM PARTS
222-1412N-A



TUNING PARTS
222-1412P-B-VC



CLEAR WY5W

222-1611P-B-C
FRONT LAMP
20PRS 1.80CFT

OEM PARTS
222-1611R/L-U



TUNING PARTS
222-1611P-B-C



CLEAR PY21W